



Technical Bulletin

All Clutches

Vehicle Type

All Passenger cars

How to Diagnose - Squeaking noise when the clutch pedal is depressed

To address the causes of a Squeaking noise when the Clutch pedal is depressed and associated components to be checked

Problem Definition

The Valeo Service Quality department have received several claims stating that after fitment of clutch sets, there is a squeaking noise that can be heard when the clutch pedal is depressed.

Upon inspection of the vehicle, it was found that there is no manufacturing defect with the clutch and the root cause of the squeaking noise is due to a faulty or worn pivot pin in the clutch pedal assembly. Attention should also be applied to the bushes, and if found to be worn should also be replaced.

