



## Technical Bulletin


### Clutch Set

Vehicle Type


Passenger Car


Smooth engagement of gearbox with engine after clutch replacement

Gearbox drive shaft



Alignment tool





Consequence at vehicle is the alignment tool not used during fitment



Difficult in engine Transmission alignment



Hard gear shifting/ Gear not able to shift



**Consequence in the Clutch disc spline**



1. **Above observation of spline damages is result of negligence of alignment tool during mounting.**
2. **Such conditions are not warrantable due to wrong fitment practice**