

Technical Bulletin

Clutch Set

Vehicle Type

PC

Diagnostic Tips - Gear Shifting Hard Complaints

Hub Splines damaged

- Hub splines damaged while fitting - Replace new clutch set
- Improper fitment technique - Ensure proper fitment, use proper lifting equipments while engaging the gearbox input shaft.

Caution: do not hit the disc or shake the gearbox while fitting.

Drive strap / return spring damaged

- Clutch cover assembly dropped during transportation - Replace the clutch set
- Improper handling - Ensure proper care during handling the clutch box.

Cover mounting holes mismatch with dowel pins

- The cover has not been located on the flywheel dowel pins correctly. -Install new clutch and ensure all flywheel dowel pins are in position and in good condition.

Do not use air tools to tighten the bolts.